

COOLING - GRILLE

2.080

GROUP NO. — DESCRIPTION — YEAR and MODEL	PRIMARY GROUP NO.	PER CAR	PART NO.	CODE
SEAL, Side Air Baffle				
60 Thru 62 10-20-80.....	2	342 1545	
(Side) 63-64 10-80.....	2.023	2	348 2428	
(Upper) 63-64 10-80.....	2.023	2	348 2426	
SEAL, Upper Air Baffle				
64 01.....	1	350 0196	
63-64 10 (Six-26" Long).....	1	348 2430	
63-64 10-80 (V8-26" Long).....	1	348 2431	
63-64 10-80 (47-5/8" Long).....	1	348 2427	
ATTACHING PARTS				
Upper Seal To Retainer				
SCREW, Tapping..... 63-64 10-80 (WAC).....	17.671	5	G455702	NA
RETAINER, Upper Air Baffle Seal (Metal)				
62-64 10-80 (WAC).....	1	348 2429	
GROMMET, Wire				
60-61 10-20-80 (1-5/16" O.D.).....	3.166	1	312 7192	
61 10-20-80 (1" O.D.).....	3.288	1	55 350	
2.080 PUMP ASSEMBLY, Water				
60 01 (LAE); 61 01 (LAC-Note 2.080-1).....	1	320 5594	
60 01 (WAE-LAC)(Heavy Duty-Note 2.016-3).....	1	320 1269	
61 01 (WAC)(Heavy Duty)(LAC-Note 2.080-2); 62 01 (LAE)(WAE-Note 2.080-3); 63 01 (LAE)(WAE-Notes 2.016-5 & 2.016-7); 64 01.....	1	320 2644	
61 01 (WAE-LAC); 61-62 01 (Heavy Duty-Note 2.016-3) ; 62 01 (WAE-Note 2.080-3 Type 1); 63 01 (WAE-Note 2.016-9).....	1	320 2972	

NOTE 2.080-1: Used Prior to Car Code No. 21119.

NOTE 2.080-2: Used beginning with Car Code No. 21119.

NOTE 2.080-3: Two Types of Water Pumps were used on the 62 01 and 62 10 OHVC built with an Autolite 40 AMP Alternator. They can be identified as follows:

Type 1: The Alternator Bracket is "L" shaped and Steel Bar Stock. The Adjusting Strap is 5-1/2" long with Two 13/32" I.D. Mounting Holes.

Type 2: The Bracket is Cast Iron and the Adjusting Strap is 3-3/4" long with One 13/32" I.D. Hole.